



**Key**

L =	800.0000	L =	400.0000
G1% =	-1.2500	G1% =	-2.4170
G2% =	-2.4170	G2% =	-4.7500
A =	-0.7292	A =	-0.2917
B =	-1.2500	B =	-2.4170
C =	1310.0000	C =	1295.3300
r =	-0.4583	r =	-0.5833

STA	X			CRV	%
64+00	0.0000			1310.00	-1.250
64+50	0.5000			1309.36	-1.323
65+00	1.0000			1308.68	-1.396
65+50	1.5000			1307.96	-1.469
66+00	2.0000			1307.21	-1.542
66+50	2.5000			1306.42	-1.615
67+00	3.0000			1305.59	-1.688
67+50	3.5000			1304.73	-1.760
68+00	4.0000			1303.83	-1.833
68+50	4.5000			1302.90	-1.906
69+00	5.0000			1301.93	-1.979
69+50	5.5000			1300.92	-2.052
70+00	6.0000			1299.88	-2.125
70+50	6.5000			1298.79	-2.198
71+00	7.5000			1297.68	-2.271
71+50	7.5000			1296.52	-2.344
72+00	8.0000			1295.33	-2.417
72+50	0.5000			1294.05	-2.708
73+00	1.0000			1292.63	-3.000
73+50	1.5000			1291.05	-3.292
74+00	2.0000			1289.33	-3.583
74+50	2.5000			1287.47	-3.875
75+00	3.0000			1285.46	-4.167
75+50	3.5000			1283.30	-4.458
76+00	4.0000			1281.00	-4.750